

To/Brimed
cc Whittle

29 May '73
19:45 Z

calibration

Run M172, as soon as possible
with the following changes.

Run a calibration per checklist
omitting step 3 (batteries & T-003)
until all five food heating trays
are in place. At this time add the
following steps -

Step 3 using mozite pads
and straps to secure batteries & T003.

Add a step by removing top food
tray.

~~Repeat~~ Do final step, ^{per C/L} with zero
added mass.

Notes - ~~Tighten~~ ~~eat~~ Insure lids are mated to
to proper trays - i.e. double red lid to
double red tray -

If feasible measure mass of
mojito pads + straps on SMMD.

At this time the data from MO74
col is missing - This data is
~~needed~~ ed -

W. Thornton
PI MO74/172

