

FLIGHT ACT OFFICER LOG		DAY	REV	PG
SITE/ACQ/LOS	NOTES			
To / Biomed				
From / P1				
Subj /	SMMD Failure & missing			
Cal.	mass.			
	electronics			
	Apparently the W.R. SMMD failed -			
	possibly after having been left on			
	overnight.			
	Trouble shooting for this failure			
	consists simply of insuring that power			
	is being applied to the unit (i.e. ck. all			
	CB's). Zero G connector could be removed			
	and reinstalled (with C.B. open) - power			
	switch should be cycled to both			
	Mass & Temp. Note whether the			
	power supply is operational by			
	presence or absence of high			
	pitched sound. This procedure			
	should be done after W.R.			
	unit has cooled to 90°F. or			
	less -			
	In the absence of 5020 film			
	pack calibration must simply			
	be done without it - <del>At this time</del>			

[illegible]