

reg +300 @ 150ma Pwr Supply

+ 105 @ 70ma

- 150 @ 30ma

Use Xfmrs from G-30 +
Reg

- 250