

7/27/55

Channel G on Offner Osc. was erratic - Replaced  
matched pair of 6517's in preamp  
two other ~~sta~~ amps were noisy + so replaced  
6517's - ~~Pre~~ Amp in Ch. A was noisy -

9/-