

701 Coward's Creek Road
Friendswood, Texas 77546

10 January 1978

Mr. Bruce Del Mar
President
Del Mar Avionics
1601 Alton Avenue
Irvine, California 92714

Subject: Property Accountability

Dear Bruce:

Over the past year I have received and returned tens of thousands of dollars worth of equipment. Each item you shipped was carefully documented with multiple documents which some bean counter undoubtedly has counted. In contrast, for the items returned, I have received only partial listing. Although we, you and I, understand the situation if you should lose a blade off the chopper, or if a wing should fall off mine, this property situation would be a mess with all kinds of legal ramifications.

The following is an inventory of all the equipment that remains in my possession from the above interchange:

- 1 each - Texas Instruments' Galvanometer Recorder
- 1 each - Portable Infusion Pump
- 1 each - Millar Coupler-Calibrator*
- 1 each - Millar 3F Catheter Tip Transducer*
- 1 each - Millar 4F Catheter Tip Transducer*
- 1 each - Prototype Avionics Pressurometer II with three batteries, one cuff and transducer
- 1 each - Avionics Holter Recorder with two batteries
- 1 each - Avionics Prototype Battery Charger for Pressurometer
- 1 each - Micron Physiological Pressure Transducer*
- 1 each - Prototype 660A Replay Unit with only tape time module

Bruce Del Mar, President
Del Mar Avionics

10 January 1978
Page 2

The T. I. recorder will be returned as soon as time allows proper packaging. I should like to borrow the asterisked items for approximately six months in hope of making some weightless physiological measurements.

An interchange of equipment will continue but hopefully at a reduced rate such that it can be properly documented both ways. As a baseline for this, please get whoever is responsible to concur on the above list (or document any supposed discrepancies) so we will have a baseline.

I dropped all the insurance coverage except for the Oxford units and now that you have them, I will drop even that. All items except two transducers and the coupler are now at UTMB. I will assume responsibility for the transducers while I keep them.

Sincerely,

W. Thornton

W. Thornton, M.D.

WT:lm