

Unfortunately the ~~comm~~ only day 1 of the
comm. tapes were transcribed and this amounts to
70 pages and more than half is crew.

The idea that the PI's weren't kept in the
loop is belied by a typical exchange on X-58
when the ^{ancient} recorder packed up an expected event in which
it had been agreed to ^{preflight} pass in another one to
~~save buying of f~~

MS - Science, MS

SE POC - SA, MS

MS - 'Year' (were) waiting for the ideas on the
recorder
POCC

whose ancient recorder died as expected preflight -

Insert P-35, 36, 37

This incident whole illustrates several
points. While it was ~~to~~ not in relaxed jargon

give the problem, solution
it took about 100 words to ^{replace} ~~repair~~ on a
large
experiment, repair + report on a failure in the
replacement, run the experiment, have ground
check it + add as I recall 15 mins. to the
time line. Apparently this PI appreciated the
scientific results.

Conversely after some 10 pages of
talk required by the inadequately prepared
calibration on 76 I tried to get the ground
to work the problem - Their apparent solution
was to ^{(continue) to try} ~~put a talk~~ talk one another through
the problems and then complain of inadequate
communication.