National Aeronautics and Space Administration

Lyndon B. Johnson Space Center Houston, Texas 77058



Reply to Attn of:

SD/90-67

April 5, 1990

Whitmore Enterprises Attn: Mr. Henry Whitmore Box 369 Route 5 San Antonio, TX 78221

Subject: Contract NAS 9-18230

Apropos our telephone conversation, my understanding of the contract is as follows:

Item 2 - Rowing machine. We are to provide drawings with dimensions and locations of the seat mounting studs where the unit is to be located and the same for the Brownline fittings.

Item 4 - Force generator. We are to supply a Brownline fitting and harness to you as well as location and dimension drawings of the mounting studs.

These GFE items were not listed in section J.1, GFE; and this will be reconciled. I have requested the items and will continue to try to obtain them as soon as possible.

Shipment of the GFE under item 5 has been repeatedly delayed by local paper work, but it is supposed to go to shipping today. We are aware that absence of these items have delayed your completion of various contract items.

It is hoped that you will receive the above items shortly.

William E. Thornton, M.D. Contract Monitor

CC: DC1/LL D

BG4/H. R. Crawford

SD/WEThornton: jrw: 4-4-90:32785