


Del Mar Engineering Laboratories

TO: Gene Hunter
FROM: Bob Murray
SUBJECT: D-100A Production Engineer

NO.: E.L.-107
DATE: October 17, 1957

1. Shop has not yet received your design of C.R.T. bracket. Please expedite!! Electronic design of the socket connection is not complete.
2. Please review installation of meter box and separation of mixer. Separation is now $1/32$ inch and your design was $1/8$ inch I believe. Suggest that $1/8$ inch might be milled from pads. This will allow box to be removed and keep cam lock studs in place.


R. E. Murray, R.E.

RHM/m

cc: F. H. McCollum (2)
A. B. Wainnesky
W. F. McAllister
File